Compression Tests: mechanical text used to determine how a moteral bottones when compressed, squarted, crusted, or Antheres.

-> form, metal, PET, PVC/ABS pipes, plastics, & mothers.

-> design process, production environment, Q.C. laboratory. Polynnethone Form Specimen Preparation: selection of the sample, prep. of sample (cutting/grinding), mounting of the sample (plates/jans), opplication of force. Key Parameters: compression dead -> (notrinsic propedies Key Regions: 1 · elastic region: behaves elastically & returns to original thope · stress (0), MPa, force applied / unit area 2 · plastic region: ofter yield pt & deforms permanently
3 · failure region: fractures & fail completely. · shain deform whative to original length, % · load: KN, N, applied to specimen. · displacement: mm, cm, movement of specimen 4 · ultimate compressive strength: Max stress before cortors trophic failure. compressive yield stress: photics -> pt of permanent yield on curve metals -> 0 coneaporally to 0.002 in/in plantic strain Measuring Hardness: resistance of underal to surface partiation · stross reeded to rupture a specimen, hade to find us interville test. Identification Hardness Test: determites resistance of interial to permanent def. when a face is applied.

-> press a hard indenter (diamond or hardoned feel) } Brinell / surface about a textury -> resulting indentation is then measured.

Rockwell Steps: propore sample -> select indenter & look -> apply the land, -> meanne identified in size & depth (microscope) -> contempte hardness value. indentation. Brinell (hardened steel ball), Rockwell (Diamond cone or hardened steel ball) Hardness (H) & Strength (T.S.): micro-indutation: Vickers (diamand pyramid), Knoop (diamand pyramid w/ larger diagonal). often correlate in bulk isotropic materials. -> most can be : very hard (surface) but borithle intenally Important Considerations: surface costition / indenter tope & lood / dwell time (springbank of moterial) / collibration (morehine) lower overall strength -> OR soft but high strength (ductile or tough) Rockwell Test: applies specified band to inhorter/meanne. -> conical indenters + wide variety of other indenters. Brinell Test: spherical indenter/ Poisson's Ratio: vortio of lateral strain to axial strain otroightformed to implement (indent & then meanne) -> select and justicionally.
-> more direct rowlds / dial reading / no colo-by-hand needs. under compression limitations: doesn't work for very soft / hard orderer, non-ideal for this openiness, -> (+) means ordered expansion at most when under compression.

O means no change in Ideral dimension when compressed.

indent edge less obvious to observe,

inaccircle for low hordress motorial, /surface hardened or parted surfaces.

Vickers Test: promid-shaped, 136-degree oper orgle in Jarter, can be used for very hard / soft materials

-> diverse meterials testing, some-there indust

-> disevery using microscope.

> Vickers Hardress (who (HV) => calc using applied load & overage dogoral trough

> Pros versatility precise hardress meanwerends, good for delicate unot. (able to use law locals), good for small scale testines (grains).

Common Application: Q.C., failing andlyris, uniteralogy.

Minor land (stabilizes sample & romae inconstituentes),
major land (real test), dapth measurement,
hardness calculation, higher hardness number = hade material

Knoop Test: microhardness test for predict a delicate month

-> dongsted paramid-thoped diamond indenter

> 1725° long & 130° short, < 1 kg very light lands

-> marnes layth of loverest indontation diagonal,

> Knoop Kardness Volhe (HK) => colk. from load & leyth Pros used for extremely small overs & delicate insterial minimizes drange to thin samples/contings (light), brittle moteral comportibility.

Application: mat research (grains/phaces), thin film analysis.

> (-): invort expersion vlan comp. (voice!).

Compressive mounts of Elasticity: slope of the elastic region of the compression test. Usually, it is > Young's

 $\mathcal{E}_{l} = \frac{\Delta l}{L}$ $\mathcal{E}_{s} = \frac{\Delta R}{L}$ $\frac{\mathcal{E}_{s}}{\mathcal{E}_{l}} = v$ Paisson's Ratio longitudinal transvoce strain strain

3- Point Flexual Test: measures below of motion a simple born looking-geometry

-> compression, tension, & their forces.

-> universal feeting machine, 3 ar 4-point bend fixture

> ease of specimen prop + tolding sendra & drain robe

Spring Testing: Quality assumance proposes.

> lood capacity / fortigue strength / spring rate

> manadanic fest w/ end-of-test critesia.

> Itaoke's Law: deform. < stress applied.

Top-Land / Crush Testing: crustes simplesto a specific distance (1/4") to determine quality.

Relevance of Compression Tests: Q.C., most characteristics, R&D, failure analysis

Impact Tests: wearne ability of most, to resist deform in response to a sudden book,

> Charpy, Izad, drop-neight, dynamic tear tests.
> find must tourghess, establish Q.C. standards.

Impact Strength: wearne of energy required to fractive mot under impact force (Joules) & topols or vol. & dist. of F

Charpy V- Notch Test: pondulum mechanism that swings

or harmer onto a V-nother sample > every obserbed during tradine

medianism that swings

home onto a V-notbed sample
every obsorbed during toodine

is in Janles

part-impact travel of the home

/ E dissipated in mys. > part-imparet travel of the hommer.

Izod Test: similar to Charpy, but vertically

-controled sample swing notch fixed jon hotel notch -calculates energy-absorption

tatigue: fail of materials by hadme if they are subjected to repeated applications of shest (90% of all metallic fractures).

Statigue testing

Cyclic land, see how many cycles to course failure

eg. servo-hydraulic fatigue tester


fatigue life = # of cycles with stood.


of cycles until failme, crade growth vale, stress- drain behavior, material properties, loading conditions, environment.

> types: static failure, low cycle fatione (local plastic strain), high cycle fatigne (local dastic strain).
> importance safe designs, predictive maintenance,


material selection.


Prop Weight Test: free falling wight deliver a single-pareful blow to the sample -> versatile & harlles various maderials -> measures resistance to shortery/deform.





Dynamic Tear Test: characterizes textiles & delamination of 30 privated products -> every to dear sample until complete failure





Impact about Forctors:

-> mosterial thickness (value) > temp (veder if hatter mostly) > noth radius (sharp, Hen TO)

Import Failures J

Brittle hardwes: hard morterial (non-plastic Jeform) -> 2+ parts Ductile fractures: duchile/tough (plastic determ) -> 2 parts/turided. Slight Cracking: success of Champy & Izod: Fracture, if not more every needed Endmae: a to the moderal's torrile strongth (not linear & Japanes on mot). for steel: TS < 200 kpsi (1400 MPa), se = 0.42*TS TS > 200 kpsi (1900 MPa), Se = content = 100 kPsi (500 MPa)

→ decenses when temp \(\) more susceptible to fatigue as Temp \(\).
 → importance sake derigns, reduced fatigue teating, material selection.
 → not all materials possess an answere limit!

